

Termination



BAPI recommends wiring the product with power disconnected. Proper supply voltage, polarity, and wiring connections are important to a successful installation. Not observing these recommendations may damage the product and will void the warranty.

BAPI recommends using twisted pair of at least 22AWG and sealant filled connectors for all wire connections. Larger gauge wire may be required for long runs. All wiring must comply with the National Electric Code (NEC) and local codes. Do NOT run this device's wiring in the same conduit as AC power wiring of NEC class 1, NEC class 2, NEC class 3 or with wiring used to supply highly inductive loads such as motors, contactors and relays.

BAPI's tests show that fluctuating and inaccurate signal levels are possible when AC power wiring is present in the same conduit as the signal lines. If you are experiencing any of these difficulties, please contact your BAPI representative

Wire color	Purpose	Note
Yellow	Temperature Sensor	Factory connection, no customer connection allowed
Yellow	Temperature Sensor	Factory connection, no customer connection allowed
Blue	Humidity Sensor	Factory connection, no customer connection allowed
Blue	Humidity Sensor	Factory connection, no customer connection allowed
Green	Voltage output	0-10VDC To Analog Input of Controller
Black	GND (Common)	0-10VDC output, Ground
Red	Power	15 to 35VDC or 15 to 24VAC

Fig. 1
Humidity Transmitter



BAPI's humidity transmitters ARE polarity sensitive as well as reverse polarity protected.

Filter Care

A 60 micron sintered bronze filter protects the humidity sensor from various airborne particles that might reduce the sensor's accuracy. Depending on the sensor's location and environment, this filter may need periodic cleaning. To do this, gently unscrew the filter from the probe. Rinse the filter under warm water until clean. Warm soapy water may be used if necessary. Gently replace the filter by screwing it back into the probe. The filter should screw all the way into the probe, or at the most have only one or two threads showing. Hand tighten only, if you over tighten you may break the probe. If a replacement filter or replacement probe is needed, call BAPI for more information.

Installation

Duct Unit in a Weatherproof Enclosure (Fig 2)

Drill a 1 inch hole for the probe in the duct and use two number 8 sheet metal screws to attach the sensor to the duct. Center the probe in its mounting hole. Be sure that the foam seals the hole, do not over tighten the screws.




Fig. 2: Duct unit in a Weatherproof (WP) Enclosure

Outside Air Unit in a Weatherproof Enclosure (Fig 3)

Do not mount in direct sunlight. Mount with the sensor probe pointed down. Drill a hole large enough for your sensor cable through your mounting surface. Mount the unit to the surface with a wiring knock out centered over the wiring hole. Pull the wiring into the unit and terminate using sealant filled connectors. Best practice is to caulk the wiring hole after the wiring is installed. Be sure that the foam on the back of the unit makes a good weather tight seal.




Fig. 3: Outside unit in a Weatherproof (WP) Enclosure



0 to 10V Duct and Outside Air Humidity Sensors

Installation and Operating Instructions

9504_ins_hum_duct_out_10V

rev. 08/20/20

Diagnostics

Possible Problems:

Unit will not operate

Humidity reading is maximum 10V or 100%

Humidity reading is minimum 0V or 0%

Humidity reading in software appears to be off more than specified accuracy

Possible Solutions:

- Check power supply/controller voltage supply
- Disconnect sensor and check power wires for proper power to the sensor
- Make sure the sensor is installed properly, and is not shorted
- Verify that the humidity sensor is installed
- **QUICK CHECK:** Short the humidity sensor connections with a wire. Does the reading change? If so, the sensor may be faulty, if not contact *BAPI* technical support
- Check all software parameters
- If available, check the sensor against a calibrated control such as a hygrometer
- Use the 0 to 10V signal formula to calculate the output
- Determine if the sensor is exposed to an external source different from the measured environment

Humidity Formula

Output	Humidity Formula
0 to 10 VDC	%RH = V/0.10